

Form 574-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

hc-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 27 W 4 Mer.

CE # 1/16 Corner common to Sections
_____, _____, and 25

Corner consists of a 4" B. Spr (red) in place

State condition 9004

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

#		#	
8		8	
1/16		1/16	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		# 8	
		1/16	
		B.T	

Species cedar

Diameter 9"

Bearing S60E

Distance 80 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

Field Ass't

(Title)

10-1-35

(Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


8071! ~~chain~~ distant.

from which this Corner bears N 60 W

side of ~~tree~~ tree

tree 9 inches diameter, on the N. W.

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 59 N R. 27 W 4 Mer. T-24

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

T-24

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 27 W 4 Mer.

8 1/16 Corner common to Sections

.....,, and 25

Corner consists of a 4" B. spr (not) in place

State condition good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 8 1/16		# 8 1/16	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		# 8 1/16	
		B.T	

Species cedar

Diameter 9"

Bearing S 60 E

Distance 80 Li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Ervin Meagher

(Signature)

Field Ass't

(Title)

10-1-35

(Date)

Lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this


80 1/2 chains distant.

from which this Corner bears N 60 W

side of tree

tree 9 inches diameter, on the NW

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 59 N R. 27 W

9

Mer.

T-24

U. S. Department of Agriculture
FOREST SERVICE

T-24

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 27 W 4 Mer.

EC (# 8) 1/16 Corner common to Sections
-----, -----, and 25

Corner consists of a 4" B.S.P.R. (net) in place
State condition good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 8 1/16		# 8 1/16	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		# 8 1/16	
		B.T.	

Species ----- cedar

Diameter ----- 9"

Bearing ----- S 60 E

Distance ----- 80 Li

Do you believe this to be a genuine Land Office Corner? ~~yes~~

If not, why? -----

Ervin Meagher

(Signature)

Field Ass't

(Title)

10-1-35
(Date)

Corner again.

Give any further facts which will aid in finding this


80 ft. ~~things~~ distant.

from which this Corner bears N 60 W

side of Tree

tree 9 inches diameter, on the NW

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 59 N R. 27 W

4

T-24 Mer.