

U. S. Department of Agriculture
FOREST SERVICE

2-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59-60 R. 26 4th Mer.

Section Corner common to Sections

31, 32, 5, and 6

Corner consists of a wooden post (~~rod~~) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
31	6	5	32

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T60N
R26W
S31

T60N
R26W
S32

T59N
R26W
S5

Species Birch Cedar Birch

Diameter 9" 8" 11"

Bearing N70°W N25E S30E

Distance .33 .75 .91

Do you believe this to be a genuine Land Office Corner? No

If not, why? Sketching on vitaceae trees show age about 10 yrs. probably county corner. No BT at base of tree

F. H. Moore
(Signature)

Feb. 7 1935
(Date)

TF
(Title)

57x6 20' high

is old blazed w/ Pine

line tree on lake shore

Corner again.

Give any further facts which will aid in finding this


23 chains distant.

from which this Corner bears S 70 E

side of Bearing tree

tree 9 inches diameter, on the SE

Metal Location Poster is on a White Birch



(Make sketch of topography near Corner)