

U. S. Department of Agriculture
FOREST SERVICE

2-5

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N. R. 26 W. 4th Mer.

Section Corner common to Sections

17, 18, 19, and 20.

Corner consists of a Wooden Stake ^{2 Iron Pipe} (not) in place

State condition Fair

Dimensions above ground 26 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
18	19	20	17
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 18	S 19		
B.T.	B.T.		

Species W.P. W.P.

Diameter 10" 14"

Bearing N71³/₄W. S28¹/₂W. True North.

Distance .63 ch. .78 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Probably County - does not check with G.L.O. Notes

Ralph R. Johnson
(Signature)


December 18, 1934
(Date)

Sub. Const. Fore.
(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears *28'*
side of *N 33 1/2 E*
tree *4* inches diameter, on the *North*
Metal Location Poster is on a *White Pine*



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Previously Posted
CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W ATH Mer.

SECTION Corner common to Sections

17, 18, 19, and 20

Corner consists of a WOODEN STAKE & IRON PIPE (not) in place

State condition FAIR

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S 18	S 19	S 20	S 17
---------	---------	---------	---------

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 18	S 19		
BT	BT		

Species Wh. P. Wh. P.

Diameter 10" 14"

Bearing N. 71 1/4 W. S 28 1/2 W. TRUE NORTH

Distance 63 ch. 78 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Ralph K. Johnson
(Signature)
December 18, 1934
(Date) SUBV. CONST. FORE.
(Title)

Corner again.

Give any further facts which will aid in finding this


..... chains distant. 28

from which this Corner bears N 33 1/2 E

side of TREE

tree 6 inches diameter, on the NORTH

Metal Location Poster is on a WHITE PINE



(Make sketch of topography near Corner)

T. 60N R. 26W Mer. 4TH