

U. S. Department of Agriculture

FOREST SERVICE

17-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W 4th Mer.

16 1/16 Corner common to Sections

, 5, and 8

Corner consists of a 4th-4 sided post (not) in place

State condition Fair (1" x 6" iron pipe)

Dimensions above ground 30" x 4" x 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S	5	8	
5	9 1/16		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

?			
B.T.	B.T.		

Species B.sp. B.sp.

Diameter 5" 4 1/2"

Bearing S 70° W S 80° E

Distance 40 links 30 links

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? There is no record in

the orig. notes for this corner.

The material is more recent than the

original survey.

J. P. Rales

(Signature)

5-20-59


(Date)

Assistant Dist Rgr

(Title)

Corner again.
Corner lies in the center
of an SX type, 3/4 chains
west of high ground - a
gravel pit.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)