

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

17-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W 4th Mer.

1/4 Corner common to Sections
5, and 8

Corner consists of a Tamarack Stake (not) in place
State condition Bottom decayed - leaning

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Condition of Stake indicated That it has Not been in For More Than 20 yrs

Leonard J. Pulkrabek
(Signature)

Oct. 30, 1934
(Date)

Tech. Foreman
(Title)

Corner again.
 Grassland is located in open
 grassland near lake
 3 stakes 4, 8 & 10 feet
 high, all standing are put in
 Next to the cor. stake.
 Very easily seen.

Give any further facts which will aid in finding this


1.80 chains distant.

From which this Corner bears Due East

side of Tree

tree 11 inches diameter, on the West

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 60N R. 26W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Robert

E-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *60 N.* R. *26 W.* *4th* Mer.

1/4 Corner common to Sections
5, and *8*

Corner consists of a *Tamarack Stake* (not) in place
State condition *Bottom decayed - leaning*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>1</i>		
	<i>4</i>		
	<i>5</i>		

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Condition of stake indicated that it has not been in for more than 20 yrs.*


Lionard J. Pulkiabit
(Signature)

Oct 30, 1934
(Date)

Lech Foreman
(Title)

Corner again.
 Corner is located in open
 grassland near lake
 3 stakes, 4, 8, & 10 feet
 high, all standing, are put in
 next to the corner stake.
 Very easily seen.

Give any further facts which will aid in finding this
 1.80 chains distant.
 from which this corner bears
 Due East
 side of
 tree 11 inches diameter, on the
 West
 Metal Location Poster is on a
 Cedar



(Make sketch of topography near Corner)

T 60N R 26W 4th Mer.