

11-9
Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *60 N* R. *26 W* *4th* Mer.

Section Corner common to Sections
16, 17, 20, and 21

Corner consists of a *wooden stake* (not) in place
State condition *Fairly sound*

Dimensions above ground *Dia-3"; Hgt-36"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>5.17</i>	<i>5.20</i>	<i>5.21</i>	<i>5.16</i>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>obliterated</i>	<i>5.20</i>	<i>5.17</i>	

Species *Non.Pine Non.Pine Soft.Pine*
Diameter *12" 8" 12"*
Bearing *S37°E S36°W N31°W*
Distance *63.4 110.2 64.6*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

D. P. Moss
(Signature)


June 12, 1934
(Date)

Tech. Foreman
(Title)

Corner about 100 South
or Big Fork Road

Corner again.

Metal Location Poster is on a
tree inches diameter, on the
side of from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. GON. R. RAIN 4th Mer.