

R-17

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W 4 th Mer.

Section Corner, common to Sections

22, 23, 26, and 27

Corner consists of a Wooden stake (not) in place

State condition Poor

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

			(.) N R 7
--	--	--	--------------------

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T60 R26 S22	T60 R26 S26
-------------------	-------------------

--	--

BT	BT
----	----

--	--

Species Birch Balsam

Diameter 10" 12"

Bearing N18 $\frac{1}{2}$ W S27 $\frac{1}{2}$ E

Distance 35 chs. .08 ch.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Probably county - BT's do

not check with GLO notes

Ralph R. Johnson

(Signature)

10/8/35


(Date)

Foreman C & M

(Title)

Corner again.
Sec. Lone posts set along Tr. Tr.
602 a on south line of Sec. 22 and
on east line of Sec. 27

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 60 N R. 26 W 4 th Mer.

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

posted

Chiquita

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 204 R. 200 4 Mer.

Corner common to Sections 22, 23, and



Corner consists of a concrete post in place
State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

Signature.

Date.

Title.

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

	Sec. 27	Sec. 27
	Sec. 28	Sec. 28

8-3027 (Make sketch of topography near Corner.)

T. M. R. S. A. Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N. R. 26W. 4th P. Mer.

Section 22, 23, 26, and 27 Corner common to Sections

Corner consists of a Scribed Post (set) in place


State condition Fair

Dimensions above ground 24 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 8"

Bearing S. 74° W.

Distance 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Golhaug

(Signature)

Jr. Civil Eng.

(Title)

7/17/37

(Date)

Corner again.

Give any further facts which will aid in finding this


0.13 chains distant.

from which this Corner bears S. 74.° E.

side of Tree

tree 6 inches diameter, on the S E

Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

T. 60N. R. 26W. 4th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

R-17
PP

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W 4th P. Mer.

Section Corner common to sections

22, 23, 26, and 27


Corner consists of a Scribed post (not) in place
State condition Fair

Dimensions above ground 24 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

187

S 27			
B.T.			

Species Birch

Diameter 8"

Bearing S74°W

Distance 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug

(Signature)

Jr. Civil Eng.


(Title)

7/17/37

(Date)

(Make sketch of topography near Corner)

T. 60N R. 26W 4th P. Mer.



Metal Location Poster is on a Balsam

tree 6 inches diameter, on the SE

side of tree

from which this Corner bears S74°E

0.13 chains distant.

Give any further facts which will aid in finding this

Corner again. Fair

Striped post

S3 S3

Section

SEM

ribbons