

U. S. Department of Agriculture
FOREST SERVICE

7-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W 4th p. Mer.

Quarter Corner common to Sections 25, and 26



Corner consists of a Cedar post (not) in place
State condition good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

B.T.

Species Spruce, Stp. Cedar Stp.

Diameter 10" 7"

Bearing N35°E N14°W

Distance 4 8

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

Jr. A. Gjelhaug
(Signature)

Jr. Civil Eng.
(Title)

7/17/37
(Date)

4 chains south of highridge
corner in swamp

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 60N R. 26W 4th p Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 25E Sec. 4th P. Mer.

Quarter Corner common to Sections 25, and 26



Corner consists of a Cedar Post (not) in place State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce Stp. Cedar Stp.

Diameter 10" 7

Bearing N35°E N14°W

Distance 4 8

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

7/17/37

(Date)

4 chains south of highridge

Corner in swamp

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 60N R. 26W 4th P. Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

T-21

Chippewa, NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *60* R. *26* *4th P* Mer.

1/4 Corner common to Sections

25, and *26*

Corner consists of a *Cedar post 4" x 4 1/2"* ~~(not)~~ in place

State condition ~~good~~ *Fair*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>1/4</i> <i>Sec</i> <i>26</i>		<i>1/4</i> <i>Sec</i> <i>25</i>
--	---------------------------------------	--	---------------------------------------

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>BT</i>			

Species *Cedar Stump*

Diameter *10"*

Bearing *N 7° W*

Distance *8 Lks*

Do you believe this to be a genuine Land Office Corner? *Yes*

~~If not, why?~~ *The scribbling on stump indicates the B.T. was put in before swamp burned over as scribbling is charred & repro. is 35 years old.*
Virgil D. Smith

(Signature)

6-25-57

(Date)

B. D. H.

(Title)

Corner again.

Give any further facts which will aid in finding this

8 Fks chains distant.

from which this Corner bears

N 99° E


side of Tree

tree 4 inches diameter, on the

East

Metal Location Poster is on a

B.F.



(Make sketch of topography near Corner)

T. 60 R. 26 4th Mer.