

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W A<sup>74</sup> Mer.

1/4 Corner common to Sections  
1, and 2

Corner consists of a ES. Post + 1/2" iron pipe (not) in place


State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASPEN Spruce

Diameter 7" 7"

Bearing N. 64° W Due East

Distance 18.1 Ks 25.1 Ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Informed this was surveyed by County.

Murbeck + Kiebitz

(Signature)

9-14-36

(Date)


Sy. F. R. A. Clerks

(Title)

Corner again.  
 Bearing trees decayed & no scribbles  
 visible. Local settlers supplied the  
 facts given & aided in finding corner  
 location.  
 E.S. corner is set in a slight  
 depression, creek approx 100 ft.  
 S.W. of corner.

Give any further facts which will aid in finding this  
 corner again.  
 26 links chains distant.  
 from which this corner bears E 41° S

side of tree.  
 tree 5 inches diameter, on the south  
 Metal Location Poster is on a *Balm of Gilead*



(Make sketch of topography near corner)


T60 P26

2/1  $\frac{1}{4}$  Aspen N64W 1814S  
SP E 2514S

F.S Post + I.P

Tag on 5" Balm - south side of  
Car is E46°50 26.14S

BTS Shagbark Scrub oak in soil  
7 inches N of ground + in slight dip.



U. S. Department of Agriculture  
FOREST SERVICE

C-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W 4th Mer.

1/4 Corner common to Sections  
1, and 2

Corner consists of a F.S. Post + Iron pipe in place


State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce ASPEN

Diameter 7" 7"

Bearing EAST N4W

Distance 25 18

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Murbeck + Niebauer


(Signature)

St. Clerks SRA

(Title)

9/14/36  
(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a Galena Alena

tree 5 inches diameter, on the South

side of tree

from which this Corner bears E 46 S

26 like east distant.

Give any further facts which will aid in finding this

Corner again.

Identifying trees were deposited  
only marked stumps remained.  
Facts were given by section data  
be also aided in finding corner  
location.

Cor post is in a small depression

corner is marked with small stump

Notes on Section

Surveyed in 18 80

T. John R. 25 W Mer.