

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

AB-6

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26 Mer.

7/8 Corner common to Sections 5, and Corner of 16 7/8

Corner consists of a _____ (not) in place 7/8

State condition fair

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Wbt. P. 2i

Diameter 1 1/2"

Bearing S 45 E - Estimated

Distance 20'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No - no survey

R. Christopher
(Signature)

7-18-55
(Date)

R. G.
(Title)

Corner again.
 North edge of post face.
 In fence here - Post + pipe
 plain. BT in post face.
 about 2 ch. east of gate
 + old road.

Metal Location Poster is on a *N.W.C.*
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)