

U. S. Department of Agriculture

FOREST SERVICE

posted
U-V-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 100 R. 26 Mer. 4

Monroe Corner common to Sections
27, and 28

Corner consists of a stone (not) in place
State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>MC</u>	<u>MC</u>		
-----------	-----------	--	--

<u>BT</u>	<u>BT</u>		
-----------	-----------	--	--

Species Shum? 18

Diameter 3"

Bearing N

Distance 5

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)


11/133
(Date)

(Title)

Dashed lines for writing.

Corner again

Give any further facts which will aid in finding this
corner again
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer. 4 R. 26 T. 60 S. 10 N. W. 10115