

U. S. Department of Agriculture

FOREST SERVICE

N-13 Posted

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 27 W ^{4th} Mer.

Section..... Corner common to Sections

15, 16, 21, and 22

Corner consists of a Dead Cedar Tree (not) in place

State condition Decaying

Dimensions above ground Di-10"; 450 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S. 16	S. 21	S. 22	S. 25
-------	-------	-------	-------

NW SW SE NE

Mound of..... is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

obliterated			

Species Birch.....

Diameter 16".....

Bearing N 61° W.....

Distance 17.4.....

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?.....

[Handwritten Signature]

(Signature)


Sept 5, 34 Lech Foreman

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this
 1.77 *k.m.* chains distant.
 from which this Corner bears *S 61° E*
 side of *Tram*
 tree *15"* inches diameter, on the *S. E.*
 Metal Location Poster is on a *Birch*



(Make sketch of topography near Corner)

T. 60N R. 22W
 4th Mer. N-13