

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

0-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 22 4 Mer.

NW 1/4 Corner common to Sections
_____, _____, and 22

Corner consists of a Stake (not) in place


State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

This was established by CCC's.

J. Hamelaine

(Signature)

12-14-39


(Date)

CCC

(Title)

Corner again.
 This corner is located
 on Hardwood Ridge North
 of Upper Hard Lake.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T 60 R 27
 Mer. 4
 0-14