

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 27 S. Mer.

Sec. Corner common to Sections

23, 24, 25, and 26

Corner consists of a I.P. & Section post in place

State condition post fair

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Hsp

Diameter 8"

Bearing N 20 E

Distance 12'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No

Ralph H. Church
(Signature)

D. F. R.
(Title)


9-28-55
(Date)

T.

R.

R-21
Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a *Aspen*

tree *7* inches diameter, on the *West*

side of

from which this Corner bears *West*

6 ft ~~chains~~ distant.

Give any further facts which will aid in finding this

Corner again.

*Line 6/20 of S. 1-75 to
Wagon Lake road. Top up on
N. side of road.*