

U. S. Department of Agriculture
FOREST SERVICE

C-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 5 Mer.

0 1/2 Corner common to Sections
6, and

Corner consists of a post (not) in place


State condition Good

Dimensions above ground Flush inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Tel. pole	Post Marker	Guy Pole	

Species	<u>Pole</u>	<u>Post</u>	<u>Pole</u>
Diameter	<u>Nail</u>	<u>Tag</u>	<u>Nail</u>
Bearing	<u>SW</u>	<u>East</u>	<u>SE</u>
Distance	<u>46.0'</u>	<u>18.5'</u>	<u>43.2'</u>

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Co. Corner.

D.W. CAMPBELL

8-13-41

(Signature)

Camp Superintendent

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

18.5 ft. ~~XXXX~~ ~~XXXX~~ distant.

from which this Corner bears

Post


side of Wood

tree inches diameter, on the

Post

Metal Location Post is on a

Post



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 : R. 25 _____ 5 Mer.

C₁ Corner common to Sections
_____, _____, _____, _____
_____ 6, and _____



Corner consists of a post (not) in place
State condition Good

Dimensions above ground Flush inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Tel. pole	Post Marker	Guy Pole	

Species	<u>Pole</u>	<u>Post</u>	<u>Pole</u>
Diameter	<u>Nail</u>	<u>Tag</u>	<u>Nail</u>
Bearing	<u>SW</u>	<u>East</u>	<u>SE</u>
Distance	<u>46.0'</u>	<u>18.5'</u>	<u>43.2'</u>

Do you believe this to be a genuine Land Office Corner? No
If not, why? Co. Corner.

D.W. CAMPBELL

(Signature)

Camp Superintendent

(Title)

8-13-41

(Date)

Corner again.

Give any further facts which will aid in finding this


18.5 ft. ~~XXXX~~ distant.

from which this Corner bears West

side of Wood

tree _____ inch diameter, on the East

Metal Location Poster is on a Post



(Make sketch of topography near Corner)