

U. S. Department of Agriculture  
FOREST SERVICE

T141 N R25 W  
A21

Shippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T141-142N R. 25 W 5th Mer.  
Section Corner common to Sections  
1, 2, 35, and 36

Corner consists of a Scribed Cedar post in place  
State condition Good

Dimensions above ground 6x6x36" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T142N	T141	T141	T142
R25W	R25W	R25W	R25W
S35	S2	S1	S36
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	NO B T, s		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*T. H. Williams*

T. H. Williams  
(Signature)

Aug. 17, 1937

(Date)

Jr. Asst. Ge. Tech.  
(Title)

Corner again.

Give any further facts which will aid in finding this

0.65 chains distant.

from which this Corner bears N 5 E

side of Tree

tree 6" inches diameter, on the South

Metal Location Poster is on a Spruce

		Sec. 3	
	Ac	Ac	
	Ac	Ac	
		Sec. 36	

(Make sketch of topography near Corner)

Mer. A-21