

U. S. Department of Agriculture
FOREST SERVICE

R-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27W-26W 5 Mer.

Sec. Corner common to Sections
24, 25, 19, and 30



Corner consists of a square post in place
State condition Good condition - sound

Dimensions above ground 4" sq. 2'6" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species B. Spruce

Diameter 7"

Bearing S. 92° E

Distance 50

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. M. K. [Signature]
(Signature)

ENGINEER
(Title)

3/1/35
(Date)

Corner again.
Fence line runs W approx 50'
N corner =


Give any further facts which will aid in finding this

chains distant.

from which this Corner bears *to chain*

side of *stump*

Metal Location Poster is on a *Iron stump*
tree *5* inches diameter, on the *South*



(Make sketch of topography near Corner)

T. 141 N. R. 27 W. 26 W. 5 Mer.