

G-21

NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 26 S Mer.

1/4 Corner common to Sections

11, and 12  
Corner consists of a post (not) in place

State condition good  
Dimensions above ground flush inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? 90

If not, why? Co. Corner

E S.H. #6

R. Deford

(Signature)

8-8-41

(Date)

(Title)

U. S. Department of Agriculture

CORNER OF THE PUBLIC SURVEY

Other corner locations

72-19-M-50A-8-1-21


Give any further facts which will aid in finding this

from which the corner bears

side of

tree 10" inches diameter, on the

Metal Location Marker is on a



(Scale sketch of topography near corner)

Mer.

R

(Page)

T