

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Pasted  
12/12/40

A-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

See Corner common to Sections  
(6), and 31

Corner consists of a brass cap (not) in place  
State condition good

Dimensions above ground level inches  
Sketch grooves, letters, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why?

*R. DeFaut*  
R. DeFaut  
(Signature)

7-30-40  
(Date)

J. E.  
(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner to the N of center line of road

Corner again.

Get any further facts which will aid in finding this

chain distant.

Post


from which the corner bears

side of

Post

tree inches diameter, on telephone pole

Metal Location Poster is on a



(Make sketch topography near corner)

Mer. A1

R.

T.