

U. S. Department of Agriculture

FOREST SERVICE

E-4

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer. 1/16 # 15

Corner common to Sections 6

-----, -----, -----, and -----

Corner consists of a G.I.O. Brass Cap in place


State condition good

Dimensions above ground flush inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species -----

Diameter -----

Bearing No B. T. S -----

Distance -----

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

-----

Gilbert Byroad

(Signature)

1-19-39

(Date)

Assistant Leader C. C. C.

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


post

from which this Corner bears corner under-neath

side of post

tree 10 inches diameter, on the south

Metal Location Poster is on a cedar fence post



(Make sketch of topography near Corner)

Mer. E-4

5

R. 27

T. 141