

U. S. Department of Agriculture
FOREST SERVICE

R-6-

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5 Mer.

Section _____ Corner common to Sections
19, 20, ~~29~~, and 30

Corner consists of a Not located (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Covered Over			

Species Aspen
Diameter 11"
Bearing East
Distance Approx. 50

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Sutton
(Signature)

3/4/35
(Date)

Engineer
(Title)

Corner again.

Give any further facts which will aid in finding the


150 chains distant.

from which this Corner bears West-Approx.

side of tree

tree 11 inches diameter, on the West

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

R-5
Mer.

5

27

R.

T. 141