

U. S. Department of Agriculture

FOREST SERVICE

~~Handwritten scribbles~~  
B-5

CHIPPEWA

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.  
1/16 # 7



Corner common to Sections 6 and 5

Corner consists of G. L. O. Brass Cap in place  
State condition good

Dimensions above ground 10" inches  
Sketch greeves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

NE 1/16 Sec. 6			
B. T.			

Species Birch

Diameter 10"

Bearing N. 36° W.

Distance 0.25 Chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Gilbert L. Byroad

(Signature)

1-6-39

(Date)

Assistant Leader C.C.C.

(Title)

Corner again.

Give any further facts which will aid in finding this


0.25 chains distant.

From which this Corner bears S. 36° E.

side of the tree

tree 10" inches diameter, on the S. E.

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 141

R. 27

S

Mer.

B-5