

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

Sec.

Corner common to Sections

32, and 33

Corner consists of a pipe and post (not) in place

State condition Good

Dimensions above ground 15 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T 141 R 26		T 140 R 26	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T140	T140		
R26	R26		
S.5	S.5		
B.T.	B.T.		

Species J. Pine W. Pine J. Pine Birch

Diameter 12" 12" 10" 3"

Bearing S54-70W S73-30E N51-36E N52W

Distance 61.4 56.00 90.00 44.2'

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Co. Cor.

D.W. CAMPBELL

(Signature)

8-8-41


(Date)

Camp Supt.

(Title)

(Make sketch of topography near Corner)

T. 141 R. 26 S. 5 Men. 2-9



B.T.'s

Metal Location Poster is on a

tree 10 inches diameter, on the S.W.

side of tree

from which this Corner bears S 53-30E.

90 ft. ~~XXX~~ chains distant.

Give any further facts which will aid in finding this

Corner again.

Tag also on N. Pine 12' - S73 E - 56'

from corner. Corner on 10th Std Parallel