

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

y-9?
or
WA

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 S. 5 Mer.
#10 1/16 Corner common to Sections
33, and

Corner consists of a (not) in place
State condition


Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 833			
B.T.			

Species Norway
Diameter 12
Bearing East
Distance 60

Do you believe this to be a genuine Land Office Corner? NO
If not, why? County Corner

R. T. Defant
RAYMOND T. DEFANT

(Signature)

Jr. Civil Engineer

(Title)

7-3-40

(Date)

