

U. S. Department of Agriculture
FOREST SERVICE

6-9 Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

$\frac{1}{4}$ Corner common to Sections 8, and 9

Corner consists of a brass cap (not) in place
State condition good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W.P. _____

Diameter 24" _____

Bearing West _____

Distance .63 _____

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

R. T. DeFant
Raymond T. DeFant

(Signature)

Jr. Civil Engineer

(Title)

7/30/40

(Date)

Corner again.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Posters on a

