

U. S. Department of Agriculture
FOREST SERVICE

F-9 posted
12/11/40

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 Mer.

#7 1/16 Corner common to Sections
8, and

Corner consists of a Brass cap & post (iron) in place
State condition good

Dimensions above ground 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N 1/16	1/16 S 8	1/16 9
N	W	S
		E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N 1/16 S 9	N 1/16 S 8		
B.T.	B.T.		

Species cedar tam.

Diameter 8" 8"

Bearing East West

Distance 20 lks 13 lks

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

R. T. Defant
Raymond T. Defant
(Signature)

8/23/40
(Date)

Jr. Civil Engineer
(Title)

Metal Location Poster is on a tree 10 inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

