

U. S. Department of Agriculture
FOREST SERVICE

J-11 P.

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 5th Mer.

Quarter

Corner common to Sections

9, and 16

Corner consists of a Nat found (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash-braken over

Diameter 10"

Bearing S.E.

Distance 100

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton

(Signature)

Engineer


(Title)

3-5-35
(Date)

Dotted lines for writing notes.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears *N.W.*
side of *tree*
tree *7* inches diameter, on the *N.W.*
Metal Location Poster is on *Aspen*



(Make sketch of topography near Corner)

Mer. J-11

T. 141N R. 27W 5th