

U. S. Department of Agriculture

FOREST SERVICE

Posted
12/11/18
C-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 S Mer.

C 1/4 Corner common to Sections

4, and

Corner consists of a not (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CC S4 W.C.			
B.T.			

Species cedar

Diameter 12"

Bearing S45°W

Distance 40 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Raymond T. Doyant
(Signature)

Jr. Civil Engineer

(Title)

8/23/40

(Date)

Bladed trees turning westerly

Corner again.

Give any further facts which will aid in finding this


corner chain distant.

from which this corner bears - S 45° W

side of

tree - 12 inches diameter, on the N.W. corner

Metal Location Poster is on a corner - S 45° W



(Make sketch of topography near corner)

Mer. C-11

5

R 87

143

T.