

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P. 12  
E-12

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.  
#15-1/16 Corner common to Sections

4, and  
Corner consists of a iron pipe (not) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

none			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	none		

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? no.

If not, why? corner consists of iron pipe  
used county

R. Defant  
(Signature)

J. E.  
(Title)

8-19-40  
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

8.00

1302

from which this Corner bears

side of


1303

tree 10 inches diameter, on the

N. E.

1304

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer. E-12

R.

T.