

U. S. Department of Agriculture

FOREST SERVICE

L-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 S Mer.

1/4

Corner common to Sections

15, and 16

Corner consists of a brass cap (not) in place

State condition good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	16		15

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

R T Deford


(Signature)

6-26-41

(Date)

25 lbs E of base line
 Highway between Gold and
 base line

Give any further facts which will aid in finding the
 chain distant.
 from which this corner bears
 N15W
 side of
 tree 1 1/2 inches diameter, on the NW
 Metal Location Poster is on a



(Make sketch of topography near corner)