

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A-13
P.

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 27 W 5 P Mer.

Section Corner common to Sections

33, 34, 3, and 4

Corner consists of a Not 177 (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

Not	177		
-----	-----	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T142N R27W S34

--

--

--

BT

--

--

--

Species W. Pine

Diameter 20

Bearing

Distance

Do you believe this to be a genuine Land Office ~~Corner~~ ^{BT} *yes*

If not, why?

Robert Pershlee

(Signature)

4/18/35

(Date)

Edward A. ...

(Title)


Corner again.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of

tree inches diameter, on the

Metal Location Poster is on a *Bearing tree*



(Make sketch of topography near Corner)

Mer. 4-13

141N R. 27W