

U. S. Department of Agriculture

FOREST SERVICE

R-157024  
12/11/40

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

1/4

Corner common to Sections

27, and 22

Corner consists of a (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P.stp N.P.stp

Diameter 24"

Bearing S4W N8W

Distance .78 .85

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

R. T. Defant

(Signature)

11-5-40

(Date)

(Title)

THE TYPE OF CORNER  
OF WHICH

Corner is

any further facts which will aid in finding this


chain distant.

from which the Corner bears

side

tree inches diameter, on the

Metal Location Poster is on a



Make sketch of topography near corner

R-15 Mer.

R.

T.