

U. S. Department of Agriculture
FOREST SERVICE

N-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

1/4

Corner common to Sections

15, and 22

Corner consists of a post & rod ~~mark~~ in place


State condition Good

Dimensions above ground 18" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? Co. corner

Raymond T. Defant
RAYMOND T. DEFANT

(Signature)

6-24-41 Agric. Aide Foreman CCC SP-5

(Date)

(Title)

South of open meadow
Corner in clump of aspen

Corner again

Give any further facts which will aid in finding this


0.23 chains distant.

from which this Corner bears S 48 E

side of corner

tree 10 inches diameter, on the N.W.

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

N-15 Mer

5

R 27

T 141