

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA

NATIONAL FOREST

A-15

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5th Mer.

14th N Quarter

Corner common to Sections

S. 34- T. 142N R27W, and S3, T141N R27W

Corner consists of a Wood Post ~~(Set)~~ in place

State condition Poor

Dimensions above ground 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1 2 S		1 2 S	
34		3	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W. Pine W. Pine _____
 Diameter 14" 18" _____
 Bearing S49°W S40°E _____
 Distance 88 links 98 links _____

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Due to the odd shape and size
of the section it is quite possible
that at one time the corner was moved.

J.P. Homola

(Signature)


Jr. Forester P-1

Dec. 4, 1935

(Date)

(Title)

T. 141 142 R. 27 S. 40 Mer. A-15
 (Make sketch of topography near corner)



Metal Location Poster is on a W. Pine tree 18 inches diameter, on the South side of Town line from which this Corner bears 0.98 chains distant. Give any further facts which will aid in finding this Corner again.