

U. S. Department of Agriculture

FOREST SERVICE

*Posted
12/11/12
U-16*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

1/6 M. C. Corner common to Sections

27, and

Corner consists of a pipe (not) in place

State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 M. C. S-27

1/16 M. C. S-27

--

--

B. T.

B. T.

--

--

Species Cedar Bush

Diameter 16" snag

Bearing N45W 5300

Distance .15 .16

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Co. Corner

R. Defant
(Signature)

11-6-40
(Date)

J. E.
(Title)

NO. 10 NORTH TO ROAD
ALSO LINE EXT. OUT
SEE DRAWING FOR

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree is inches diameter, on the

Metal Location Post is on a



Sketch of location of property near Corner

Mer. U-16

R.

T.