

Form 974-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Posted  
12/11/40  
T-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 S. 5 Mer.

#8 1/16 Corner common to Sections  
27, and \_\_\_\_\_

Corner consists of a \_\_\_\_\_ (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 S27			

Species bas \_\_\_\_\_

Diameter 12" \_\_\_\_\_

Bearing S20W \_\_\_\_\_

Distance 30.7 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no

If not, why? Company Corner

R. Defant  
R. Defant (Signature)


10-31-40

(Date)

(Title)

[Faint, mostly illegible text on lined paper, possibly bleed-through from the reverse side.]

Metal Location Poster is on a tree inches diameter, on the side of [illegible] from which this corner bears [illegible] that is distant. Give any further facts which will aid in finding this corner again.



(Make sketch of topography near corner)

Mer. T-16

R.

T.