

U. S. Department of Agriculture  
FOREST SERVICE

N-21

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

Section Corner Corner common to Sections  
23, 13, 14, and 24


Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 24			
B. T.			

Species Bass

Diameter 10"

Bearing S 23° E

Distance 15 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Corner not found

original B. T.

*Raymond T. Defant*

RAYMOND T. DEFANT

(Signature)

12-27-39

(Date)

Jr. Civil Engineer

(Title)

About 500 feet South of lake  
and old buildings

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.15

from which this Corner bears


N 23° W

side of

Corner

tree 8 inches diameter, on the S. E.

Metal Location Poster is on a Bass P. T.



(Make sketch of topography near Corner)

T. 141

R. 27

5

Mer. N-21