

U. S. Department of Agriculture

FOREST SERVICE

*J. S. Shandy  
Postoff*

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 26-27 W 5th Mer.

Section Corner common to Sections

12, 13, and 18

Corner consists of a **Wooden post** in place



State condition **Poor**

Dimensions above ground **26** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species **Basswood**

Diameter **18"**

Bearing **S. 51 P. 3**

Distance **1 chain**

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*Harrison Adams*  
**Harrison Adams**

(Signature)

**3/31/36**

(Date)

*Chief of Party*  
(Title)

the end of road.

Corner is in a small pot-hole at

Corner again.

Give any further facts which will aid in finding this

chains distant.


1.00

from which this Corner bears N 51 W

side of tree

tree 18 inches diameter, on the N.W.

Metal Location Poster is on a Basswood



(Make sketch of topography near Corner)

T-25

T. 141 N. R. 26 W. 5th Mer.