

U. S. Department of Agriculture  
FOREST SERVICE

N-20,24

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

M. C. # 6 Corner common to Sections  
14, and 23


Corner consists of a (not) in place  
State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B. T.			
-------	--	--	--

Species White Pine Stump

Diameter 14"

Bearing N 80° E

Distance 20 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No corner found

*Raymond T. DeFaut*

RAYMOND T. DEFANT

(Signature)

Jr., Civil Engineer

(Title)

12-27-39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.35

from which this Corner bears S 85° E

side of Corner

tree 15 inches diameter, on the N. W.

Metal Location Poster is on a Red Pine



(Make sketch of topography near Corner)

N. 20.21

Mer.

5

27

R.

T. 141