

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted
12/1/40
U+U-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

MC Corner common to Sections
27, 27, and 26

Corner consists of a (not) in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B. T.			

Species Aspen

Diameter 8 1/2 p

Bearing N13W

Distance 11

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

R. DeFaut
R. T. DeFaut

(Signature)

J. E.

(Title)


11-6-40

(Date)

Faded text at the top of the page, possibly a header or title.

Telephone Line Section Line
North of No. 1
Corner again.

Give any further facts which will aid in finding the
chain's distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)