

U. S. Department of Agriculture
FOREST SERVICE

Chip Pur. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1A R. 29/28 5th Mer.

1/4 Corner common to Sections
30, and 25

Corner consists of a Pipe and Cap (not) in place
State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

O. G. Quam

(Signature)

3/21/35

(Date)

T-1

Eng
(Title)

located on Knoll.

County Survey
Pipe & North of
G.L.O. Corner.


Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears $1/2$
East

side of Road
tree 6 inches diameter, on the East
Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 1A1 R. 29128 S 4th T-1 Mer.