

U. S. Department of Agriculture

FOREST SERVICE

D 2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

~~S.W.~~ 1/16 \*\* // Corner common to Sections

-----, -----, -----, ~~and~~ 6-----

Corner consists of a 1" I.M. & brass (not) in place  
State condition good cap

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 S6			
B.T.			

Species R. Pine -----

Diameter 10" -----

Bearing N60°E -----

Distance 30 lks. -----

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? -----

*Arthur T. Johnson*

Arthur T. Johnson  
(Signature)

Semi-skilled Worker

(Title)

4/9/38

(Date)

D-2

*WJH*

Corner again.

Give any further facts which will aid in finding this

chains distant.

0°30'


S60°W

from which this Corner bears

side of

tree 10 inches diameter, on the

Metal Location Poster is on a Red Pine



(Make sketch of topography near corner)

T. 141 N

R. 28 W

Mer. 5th

D-2