

U. S. Department of Agriculture

FOREST SERVICE

C3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 28 W 5th Mer.

Center 1/4 Corner common to Sections

-----, -----, -----, ~~6~~ 6

Corner consists of a 1" I.M. & brass ~~(cap)~~ in place

State condition good cap

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C. 1/4 S6			
B.T.			

Species R. Pine -----

Diameter 6" -----

Bearing S79°E -----

Distance 102 lks. -----

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Arthur T. Johnson

Arthur T. Johnson

(Signature)

Semi-Skilled Worker

(Title)

7/10/38

(Date)

C-3

up

Corner again.

Give any further facts which will aid in finding this

chains distant.


1.02

from which this Corner bears S79°E

side of

tree 6 inches diameter, on the

Metal Location Poster is on a Red Pine

			<p>Sec.</p>
	<p>Sec.</p>		<p>Sec.</p>

(Make sketch of topography near Corner)

T. 141 N.

R. 28 W.

5th

Mer.