

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 141 N R. 28 W 5 Mer.

14 Corner common to Sections
5, and 6Corner consists of a 1" IP w/ brass Cap (not) in place
State condition good


Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species None

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Corner again.

Give any further facts which will aid in finding this

chains distant.


1.86

from which this Corner bears 50° 47'

side of

tree 10 inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 141 N. R. 28 W. Mer. 5

C-5