

U. S. Department of Agriculture

FOREST SERVICE

A-5
John J. [unclear]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T/41N-142NR. 28W 5 Mer.

Sec Corner common to Sections
31, 32, 5, and 6


Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen N. Pine (stump 2' high)*

Diameter *8.5" 30"*

Bearing *N(?) E S(?) W*

Distance *1.5 ch 1 ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

H. W. [unclear]

(Signature)

ENGINEER

(Title)

3/13/35

(Date)


A-5

SECTION OF THE
 TOWN OF
 COUNTY OF
 STATE OF

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

NONE



(Make sketch of topography near Corner)

TWIN-192N R. 28 W

5

Mer. A-5