

U. S. Department of Agriculture
FOREST SERVICE

A-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T 141N-142N R. 28 Mer.

YH Corner common to Sections
32, and 5

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 1/4

B. 7

Species N. Pine

Diameter 10"

Bearing N 60 W

Distance 50'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. M. S. Oley
(Signature)

ENGINEER

(Title)

3/13/35

(Date)


A-7

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
OFFICE OF THE PUBLIC LANDS

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a

NONE



(Make sketch of topography near Corner)