

U. S. Department of Agriculture
FOREST SERVICE

7-12-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *28W* *5th* Mer.

Sec. Corner common to Sections
17, 16, 21, and 20

Corner consists of a *Brass plate* (not) in place
State condition *O.K.*

Dimensions above ground *2 1/2" dia.* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

3/26/35
(Date)

N-9


W. M. ...
(Signature)

ENGINEER
(Title)

Location Poster on fence
 Post 9.5" dia. immediately East
 of plate.
 Corner again

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.

Give any further facts which will aid in finding this



(Make sketch of topography near Corner)