

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Plot T-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *28* Mer.

1/4 Corner common to Sections
27, and *28*

Corner consists of a *1/4 in* (rod) in place

State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>27</i>			
<i>BT</i>			

Species *N. Pine*

Diameter *1 1/2"*

Bearing *S 40 E*

Distance *254*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

G. Sherman

(Signature)

Engineer

(Title)

3/15/35
(Date)

T-13

B.T. large Nov. Pine on
lower east side of Gray Lake.

Corner again.


Give any further facts which will aid in finding this
chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a Becking, Tyler



(Make sketch of topography near Corner)