

U. S. Department of Agriculture
FOREST SERVICE

Plotted P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 Mer. 1/4
Corner common to Sections 21, and 22

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4 S</u> <u>21</u>	<u>1/4 S</u> <u>22</u>		
<u>BT</u>	<u>BT</u>		

Species PINE Pop STB

Diameter 14" 9"

Bearing 222W S30E

Distance 190L 130L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. Sherman

(Signature)

3/15/35

(Date)

Engineer

(Title)

P-13

SECTION 21
 T. 141 N.
 R. 28 E.
 Mer.

Corner again.


Give any further facts which will aid in finding this chain distant.

from which this Corner bears N 80 E

side of STAB

two 18 inches diameter, on the EAST

Metal Location Poster is on a PLAC STAB



(Make sketch of topography near Corner)