

U. S. Department of Agriculture

FOREST SERVICE

X16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 28 W. 5th Mer.

C.S. 1/16 # 8 Corner common to Sections

33 34

Corner consists of a Rock 8" square (33) in place


State condition Good

Dimensions above ground flush with ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? ~~yes~~ **no**

If not, why? Apparently set by County Engineer.

Arthur T. Johnson
Arthur T. Johnson
(Signature)

Semi-skilled Worker
(Title)

4/5/38

(Date)


X-16

WJA

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

This corner is at the N.E. fence corner just back of school house in Longville.



(Make sketch of topography near Corner)

T. 141 N R. 28 W 5th Mer.

X-16